


# Mounting



- ▶ CRADLES & TURNSTILE UPRIGHTS both mount to the machine with a BASE PLATE
- ▶ The BASE PLATE bolts to blocks on top of your machine
- ▶ Position your CRADLE or TURNSTILE UPRIGHT so it is offset towards the face side of your machine
- ▶ Be sure to use the proper hardware included; spacer, flat washer, lock washer, bolt